RISO INC. **TECHNICAL RECOMMENDATIONS**

Subject: Fuse Panel | Bulletin No: 46

☐ Factory Modification ☐ Field Modification ☐ Safety Information ☐ Technical Information ■ General Information ☐ Adv. Tech Information	Applies to: 3500	Modification Schedule: ☐ TBS ☐ Next Call ☐ Next PM ☐ As Necessary	Factory Installed _____ Field Installed _____ Fitting Time _____

PANEL

Fuse	Rate	Volt	Symptom
1			No Use
2	2A	12	Replace Master Roll
3	3A	24	Original Jam
4	2A	24	No Storage Fan
5	2A	5	Dead Op Panel
6	3A	24	No Feed Clutch

No Elevator Tz



DRIVE

Fuse	Rate	Volt	Symptom
1	2A	5	LCD Dead
2	2A	12	Black Copy
3	2A	-12	Black Copy



Issue Date	Effective Date	Supersedes Bulletin	Date	Page No.
5/22/89	5/22/89		5/22/89	1 of : 1